


Standard Reliability Prediction Report

Part Number System
Reference Des BCX11
Date 十一月 30, 2015
Environment GF, GU - Ground Fixed, Uncontrolled
Temperature 30.00



Description
File Name BCX11_21.5.RPJ
Time 12:33 下午
Failure Rate 24.079487
MTBF 41,529

Assembly Name	Part Number	Ref Des	Qty	Failure Rate	MTBF
System	System	BCX11	1.00	24.079487	41,529
Panel	AC60001DQ0H	21.5"	1.00	19.155620	52,204
Adapter	PK100015U0H	ADP-65JH	1.00	0.872659	1,145,923
MB	DA80015A00H	LA-D271P	1.00	4.051207	246,840